

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 2

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 115+00, 6' Rt. CENTERLINE

Oc 25-18

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.7'	1	Wet firm brown fine sandy silt w/some coarse sand, trace of gravel.	A-4 (0)	
			2			
			3			
		2.0'	4			
----- 23" Recovery						
	2	2.0'	2	Wet firm brown fine sandy silt w/some coarse sand, trace of gravel.	A-4 (0)	
			4			
			3			
		4.0'	3	----- 22" Recovery		
	3	4.0'	5	Wet stiff gray fine sandy silt w/trace of coarse sand.	A-4 (0)	
			5			
			7			
		6.0'	8	----- 20" Recovery		
	4	6.0'	9	Wet medium dense gray fine to coarse sand w/some gravel and silt.	A-2-4 (0)	
			9			
			6			
		8.0'	6	----- 15" Recovery		
	5	8.0'	5	Saturated stiff brownish gray silt w/some fine sand and clay, trace of gravel and coarse sand.	A-4 (4)	
			5			
			7			
		10.0'	5	----- 22" Recovery		

(END)

BORING NO. B # 2
SURFACE ELEV. + 39.4'