

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 23

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 338+00, CENTERLINE

0c25-19

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
	1	0.8'	2	Moist firm brown fine sandy silt w/some	A-4 (0)	
			2	coarse sand, trace of gravel.		
		2.0'	4			
----- 21" Recovery -----						
	2	2.0'	3	Moist loose brown fine sand w/some silt	A-2-4 (0)	
			4	and coarse sand.		
		4.0'	6			
----- 24" Recovery -----						
	3	4.0'	8	Wet stiff brown fine sandy silt w/some	A-4 (0)	
			7	coarse sand.		
		6.0'	10			
----- 22" Recovery -----						
	4	6.0'	9	Wet stiff brownish gray fine sandy silt	A-4 (3)	
			5	w/some clay, trace of coarse sand and		
			7	gravel.		
		8.0'	7			
----- 20" Recovery -----						
	5	8.0'	5	Wet medium dense brown fine to coarse sand	A-2-4 (0)	
			7	w/some silt, trace of gravel.		
			20			
		10.0'	15			
----- 14" Recovery -----						
(END)						

BORING NO. B # 23
SURFACE ELEV. + 41.1'