

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. SWM # 1

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 117+25, 125' Lt. CENTERLINE

0c25-20

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.5'	2	Moist loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	
			3			
			4			
		2.0'	4	18" Recovery		
	2	2.0'	4	Moist medium dense brown fine sand w/some silt and coarse sand.	A-2-4 (0)	
			5			
			6			
		4.0'	6	22" Recovery		
	3	4.0'	5	Wet stiff brownish gray fine sandy silt w/trace of coarse sand and gravel.	A-4 (0)	
			6			
			6			
		6.0'	5	20" Recovery		
	4	6.0'	7	Wet very stiff brownish gray fine sandy silt w/some coarse sand, trace of gravel.	A-4 (0)	
			8			
			13			
		8.0'	15	18" Recovery		
	5	8.0'	8	Wet medium dense gray clayey fine sand w/some coarse sand, trace of gravel.	A-2-6 (0)	
			13			
			16			
		10.0'	14	20" Recovery		

(END)

BORING NO. SWM # 1
SURFACE ELEV. + 41.9'