

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 17

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 210+00, CENTERLINE

0c25-21

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.7'	1	Wet firm brownish gray fine sandy silt w/some coarse sand and clay, trace of gravel.	A-4 (0)	
			3			
		2.0'	4			
12" Recovery						
	2	2.0'	3	Wet medium dense brownish gray clayey fine to coarse sand w/trace of gravel.	A-2-6 (0)	
			7			
		4.0'	3			
16" Recovery						
	3	4.0'	3	Wet loose brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
			5			
		6.0'	6			
20" Recovery						
	4	6.0'	6	Wet medium dense brown coarse to fine sand w/some silt, trace of gravel.	A-2-4 (0)	
			8			
		8.0'	7			
20" Recovery						
	5	8.0'	4	Saturated loose brown coarse to fine sand w/some silt, trace of gravel.	A-2-4 (0)	
			3			
		10.0'	4			
22" Recovery						

(END)

BORING NO. B # 17
SURFACE ELEV. + 40.5'