

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 4

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 202+50, 6' Rt. CENTERLINE

025-22

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.7'	1	Wet very loose brown silty fine to coarse sand.	A-2-4 (0)	
			1			
		2.0'	2			
----- 22" Recovery -----						
	2	2.0'	1	Wet very loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	
			1			
		4.0'	2			
----- 20" Recovery -----						
	3	4.0'	3	Wet firm brown fine sandy silt w/trace of coarse sand.	A-4 (0)	
			2			
		6.0'	5			
----- 24" Recovery -----						
	4	6.0'	3	Wet stiff brownish gray fine sandy silt w/trace of coarse sand and clay.	A-4 (0)	
			3			
		8.0'	7			
----- 24" Recovery -----						
	5	8.0'	6	Wet medium dense brownish gray silty fine sand w/trace of coarse sand and gravel.	A-2-4 (0)	
			9			
		10.0'	9			
----- 24" Recovery -----						

( END )

BORING NO. B # 4  
SURFACE ELEV. + 42.7'