

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 6

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 31+75, 54' Rt. CENTERLINE

OC25-24

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/2/04	1	0.7'	7	Moist very stiff brown fine sandy silt w/some coarse sand, trace of gravel and clay.	A-4 (0)	
			9			
		2.0'	10			
14" Recovery						
	2	2.0'	4	Moist loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	
			4			
		4.0'	2			
20" Recovery						
	3	4.0'	3	Wet loose brown fine sand w/some silt and coarse sand, trace of gravel.	A-2-4 (0)	
			4			
		6.0'	4			
24" Recovery						
	4	6.0'	3	Wet loose brown silty fine sand w/trace of coarse sand and gravel.	A-2-4 (0)	
			2			
		8.0'	5			
24" Recovery						
	5	8.0'	4	Saturated loose brown silty fine sand w/some coarse sand.	A-2-4 (0)	
			3			
		10.0'	2			
22" Recovery						
(END)						

BORING NO. B # 6
SURFACE ELEV. + 41.9'

list