

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 3

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 122+50, 12' Rt. CENTERLINE

0c25-25

DAILY PROGRESS	NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.0'	2	Moist loose brown silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	
			3			
		2.0'	3			
----- 22" Recovery						
	2	2.0'	6	Wet firm brown fine sandy silt w/trace of gravel.	A-4 (0)	
			5			
		4.0'	3			
----- 18" Recovery						
	3	4.0'	6	Wet very stiff brownish gray fine sandy silt w/trace of coarse sand.	A-4 (0)	
			8			
		6.0'	10			
----- 22" Recovery						
	4	6.0'	11	Wet medium dense brownish gray silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	
			10			
		8.0'	10			
----- 24" Recovery						
	5	8.0'	5	Wet medium dense brownish gray silty fine sand w/trace of coarse sand.	A-2-4 (0)	
			5			
		10.0'	8			
----- 22" Recovery						
----- ( END ) -----						

BORING NO. B # 3  
SURFACE ELEV. + 42.4'