

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 5

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 130+00, 24' Rt. CENTERLINE

Oc 25-28

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/9/04	1	0.7'	1	Wet firm brownish gray clayey fine sandy	A-4 (1)	
			1	silt w/some coarse sand, trace of gravel.		
			2			
		2.0'	3			
18" Recovery						
	2	2.0'	3	Wet medium dense brown silty fine sand	A-2-4 (0)	
			6	w/some coarse sand, trace of gravel.		
			6			
		4.0'	8			
24" Recovery						
	3	4.0'	11	Wet medium dense brown silty fine to	A-2-4 (0)	
			7	coarse sand w/trace of gravel.		
			7			
		6.0'	9			
24" Recovery						
	4	6.0'	7	Wet medium dense brown coarse to fine sand	A-2-4 (0)	
			7	w/some silt, trace of gravel.		
			8			
		8.0'	8			
22" Recovery						
	5	8.0'	6	Saturated medium dense brown fine to coarse	A-2-4 (0)	
			7	sand w/some silt, trace of gravel.		
			5			
		10.0'	5			
24" Recovery						
( END )						

BORING NO. B # 5  
SURFACE ELEV. + 39.8'