

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 21

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 322+00, CENTERLINE

0c 25-30

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/3/04	1	0.7'	1	Wet firm brown fine to coarse sandy silt	A-4 (0)	
			2	w/some clay, trace of gravel.		
			2			
		2.0'	3			
22" Recovery						
	2	2.0'	4	Wet loose brown silty coarse to fine sand	A-1-b (0)	
			3	w/trace of gravel.		
			4			
		4.0'	7			
24" Recovery						
	3	4.0'	7	Wet medium dense brown silty fine to	A-2-4 (0)	
			6	coarse sand w/trace of gravel.		
			7			
		6.0'	6			
24" Recovery						
	4	6.0'	4	Saturated medium dense brown silty fine	A-2-4 (0)	
			6	sand w/some coarse sand, trace of gravel.		
			7			
		8.0'	8			
24" Recovery						
	5	8.0'	4	Saturated medium dense brown fine sand	A-2-4 (0)	
			6	w/some coarse sand and silt, trace of		
			5	gravel.		
		10.0'	6			
20" Recovery						
( END )						

BORING NO. B # 21  
SURFACE ELEV. + 40.8'