

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 11

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 21+25, 55' Rt. CENTERLINE

Oc 25-34

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/2/04	1	1.0'	6	Wet very stiff gray fine to coarse sandy silt w/trace of gravel and clay.	A-4 (0)	
		2.0'	8			
----- 12" Recovery -----						
	2	2.0'	3	Wet very loose brown silty coarse to fine sand w/trace of gravel.	A-2-4 (0)	
			2			
		4.0'	3			
----- 22" Recovery -----						
	3	4.0'	2	Wet very loose brown coarse to fine sand w/some silt, trace of gravel.	A-2-4 (0)	
			2			
		6.0'	2			
----- 22" Recovery -----						
	4	6.0'	3	Wet loose brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
			2			
		8.0'	5			
----- 22" Recovery -----						
	5	8.0'	4	Wet loose brown coarse to fine sand w/some silt, trace of gravel.	A-2-4 (0)	
			4			
		10.0'	4			
----- 20" Recovery -----						
(END)						

BORING NO. B # 11
SURFACE ELEV. + 41.7'