

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. B # 10

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS  
BORING LOCATION: STA. 16+00, 55' Lt. CENTERLINE

0c25-36

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/2/04	1	0.7'	6	Moist medium dense brownish gray silty fine to coarse sand and gravel.	A-2-4 (0)	
		2.0'	10			
			5			
14" Recovery						
	2	2.0'	4	Wet stiff gray fine sandy silt w/some coarse sand, trace of clay and gravel.	A-4 (0)	
			4			
			5			
		4.0'	8			
24" Recovery						
	3	4.0'	4	Wet stiff brownish gray fine sandy silt w/some coarse sand and clay, trace of gravel.	A-4 (1)	
			6			
			5			
		6.0'	7			
24" Recovery						
	4	6.0'	10	Wet medium dense brownish gray fine sand w/some gravel, coarse sand and clay.	A-2-4 (0)	
			13			
			11			
		8.0'	8			
24" Recovery						
	5	8.0'	7	Saturated medium dense brown silty coarse to fine sand w/trace of gravel.	A-2-4 (0)	
			7			
			7			
		10.0'	7			
24" Recovery						

( END )

BORING NO. B # 10  
SURFACE ELEV. + 41.1'