

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. SWM # 3

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 314+25, 150' Lt. CENTERLINE

Oc 25-40

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G. I.	REMARKS
11/3/04	1	0.0'	2	Wet soft gray fine sandy silt w/some coarse sand, trace of clay and gravel.	A-4 (0)	
			2			
			2			
		2.0'	2			
20" Recovery						
	2	2.0'	3	Wet stiff gray fine sandy silt w/some clay, trace of coarse sand and gravel.	A-4 (0)	
			5			
			6			
		4.0'	7			
22" Recovery						
	3	4.0'	5	Wet very stiff brownish gray fine sandy silt w/trace of coarse sand, gravel and clay.	A-4 (0)	
			7			
			11			
		6.0'	12			
24" Recovery						
	4	6.0'	5	Wet medium dense brown fine sand w/some coarse sand and silt, trace of gravel.	A-2-4 (0)	
			12			
			7			
		8.0'	6			
20" Recovery						
	5	8.0'	3	Saturated loose brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
			2			
			5			
		10.0'	5			
24" Recovery						

(END)

BORING NO. SWM # 3
SURFACE ELEV. + 38.6'