

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 3

BORING NO. S # 3B

CONTRACT: 22-124-06 U.S. 13/404 INTERSECTION REALIGNMENT AND BRIDGEVILLE SERVICE ROADS
BORING LOCATION: STA. 313+63, 40' Lt. CENTERLINE

0c 25-46

DAILY PROGRESS	SAMPLE NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
11/4/04	1	4.0'	4	Moist medium dense brown fine sand w/some	A-2-4 (0)	
			5	coarse sand and silt, trace of gravel.		
			6			
		6.0'	8			
20" Recovery						
	2	9.0'	1	Saturated very loose brown fine to coarse	A-2-4 (0)	
			2	sand w/some silt, trace of gravel.		
			2			
		11.0'	2			
24" Recovery						
	3	14.0'	3	Saturated very loose brown fine to coarse	A-2-4 (0)	
			2	sand w/some silt, trace of gravel.		
			2			
		16.0'	3			
24" Recovery						
	4	19.0'	2	Saturated loose brown coarse to fine sand	A-1-b (0)	
			3	w/trace of silt and gravel.		
			4			
		21.0'	4			
20" Recovery						
	5	24.0'	5	Saturated loose brown coarse to fine sand	A-1-b (0)	
			4	w/some gravel, trace of silt.		
			4			
		26.0'	5			
20" Recovery						
	6	29.0'	2	Saturated loose brown coarse to fine sand	A-1-b (0)	
			3	w/trace of silt and gravel.		
			4			
		31.0'	5			
18" Recovery						
	7	34.0'	3	Saturated loose brown coarse to fine sand	A-1-b (0)	
			3	w/trace of silt and gravel.		
			4			
		36.0'	5			
18" Recovery						

BORING NO. S # 3B
SURFACE ELEV. + 38.5'