

Od 32-3

Test Drilling - Gravelly Fork
#3 about $\frac{1}{2}$ mi. south of intersection
at Del. 18 and 533 at bend in road
by power pole 66 - 17' from center
line of road at end of little white
fence.

Od 32-3

Drilling Log

0	-	1	blackish gray rather uniform fine to medium quartz sand, some lignite
1	-	2	brown rather uniform fine to medium quartz sand, fine lignite
2	-	4	same but not as uniform. Black fines but no lignite - damp
2	-	6 $\frac{1}{2}$	same, many black fines
6 $\frac{1}{2}$	-	7 $\frac{1}{2}$	tan fine quartz sand, many black fines
7 $\frac{1}{2}$	-	9 $\frac{1}{2}$	light tan fine quartz sand, many black fines
9 $\frac{1}{2}$	-	12 $\frac{1}{2}$	grey brown clayey fine sand, black fines
12 $\frac{1}{2}$	-	14	brown medium sand, no black fines
14			water table
14	-	16	light brown medium clay, sand feldspar quartz, black fine
16	-	19	well sorted medium clay, sand coarser than before, light brown. Occasional gravel.
19	-	24	light brown medium clay, sand black fines, feldspar, good sand, well sorted.
24	-	29	same feldspar
29	-	34	same
34	-	39	same only more grayish in color, occasional gravel.
39	-	49	same lost grayish color back to light brown, rusty. 47' gravel
49	-	59	fine medium and coarse sand grit and gravel, black fines, light brown, feldspar quartz, soupy for first time may be water table.
59	-	68 9	same not so soupy
69	-	79	same
79	-	94	fairly well sorted medium clay, sand, light brown, feldspar quartz black fine.
94	-	104	light brown, M.C. angular sand & some grit-black fine, Feldspar quartz.
104	-	114	same