WELL NO. PC52-8 PERMIT

OWNER Nanticoke Project - RRJ

LOCATION

DRILLER AHF UofD DATE DRILLED 7/30/68

ELEV. 16.27 PROD.

T. D. 30 REMARKS

| Depth | Description |
|---|---|
| | soil, sand, sandy w/bits & bon, w/organic matter |
| | as above but less organic surface may be disturbed to some depth |
| 4.5± | sand, m-f, silty & clayey w/a few small pebbles, tan-brn |
| 6 | sand, m, silty clayey, gray-tan |
| 7.5 | sand, m, w.s., some silt & a few small pebbles, tan |
| 8.5± | sand, c-v.c, clean, gray |
| 10.3 | gravel at 10.3 becoming coarser to m' gravel, f-m w/v.c. sand |
| 14 | light gray |
| | sand, v.c.-c, w/gravel light gray |
| 18 | sand, m, w/gravel, very silty, clayey light gray |
| 18.5 | sand, v.c.-c, gravelly, light gray |
| 19.5 | sand, v.c.-c, gravelly, brn-tan |
| 25 | |
| 27 | gravel |
| 28.25±2 | sand, brn, v.c., w/much fine gravel |
| 28.75 | clay, light gray w/lenses of very f. sand & some pieces of lef orange sand |
| 29.25 | sand m-f, silty, yellow brn |
| 30 | sand, m, w.s., silty, yellow |