MAIL TO:
WATER SUPPLY BRANCH
DIVISION OF WATER RESOURCES
P.O. BOX 1401
DOVER, DELAWARE 19903

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS AFTER CONSTRUCTION DATE.

MONITOR WELL COMPLETION REPORT

PLEASE PRINT OR TYPE

PERMIT NO. 82205 LOCAL ID 14
Owner LARRY'S HOMES INC
Address P.O. BOX 617
City SMYRNA State DE Zip 19977
Telephone Number 302-653-2601
Consulting Firm/~~Supervising Geologist~~ (If applicable)
TATMAN + LEE
Telephone Number 302-791-0700
Well Contractor DELMARVA DRILLING CO.
Date of Completion 4/3/90
Name of DNREC Contact Person N/A
Drilling Method MUD ROTARY

IS COMPLETED WELL LOCATED AS SHOWN ON APPLICATION FORM? YES [✓] NO [ ]
IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.

Pd 32-3
SEE

WELL CONSTRUCTION

Total depth drilled: 20'
Depth to water: 3'
Surveyed Top of Casing Elevations
N/A (Inner) (Outer) Ft. above Sea Level

CASING SEQUENCE

	Inner casing	Outer casing
Casing top	2'	
Casing bottom	12'	
Casing diameter	~~PVC~~ 4"	
Casing material	PVC	

SCREEN SEQUENCE

	Inner casing	Outer casing
Screen top	10'	
Screen bottom	20'	
Screen diameter	4"	
Screen material	PVC	

Type of Grout CLAY from 0 to 8
Gravel pack interval from 8' to 20'
Aquifer/Formation screened in: Pleistocene
Type of samples (ditch, split spoon, etc.)
N/A

Samples Logged By: N/A (Name)
(Title) (Company)

Well Drilled By: Delmarva Drilling Co. (Company Name)

Brad Hartman 4/3/90
(Signature of Driller in Charge) (Date)

DRILLERS LOG DESCRIP.	TOP OF STRATA	BOTTOM
Top soil	0	1
Red-tan sand	1	7
med to coarse white sand	7	20

RECEIVED
APR 9 1990
WATER SUPPLY

SUPPLEMENTAL DRILLERS LOG ATTACHED?
YES [ ] NO [✓]
PAGE 1 OF 1 PAGES

White - Water Supply • Canary - Other • Pink - Owner • Goldenrod - Contractor

Doc. No. 40-08/88/05/03