MAIL TO:

WATER SUPPLY SECTION
DIVISION OF WATER RESOURCES
P.O. BOX 1401, 89 KINGS HIGHWAY
DOVER, DELAWARE 19903
PHONE: 302-739-3665
FAX: 302-739-2296

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

FORMATION LOG

Pd43-05

PAGE _____ OF _____ PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED

PERMIT# 155807-W | LOCAL ID#

PROPERTY OWNER Burton Messick

WELL CONTRACTOR Kenny Wood | LIC# 101

DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
Top Soil	0	2
Tan Sand	2	20
Coarse Tan Sand Tbd	20	57
Med.-Coarse Sand	57	95
Coarse dark tan sand Tbd	95	125

see Pd43-04 for Data @ 131'

RECEIVED
MAR 03 1998
WATER SUPPLY

OTHER COMMENTS:

5

I HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT

Signature of Well Driller In Charge | License# 778 | Date 2/23/98

White - DNREC • Canary - Contractor • Pink - Owner

Doc. No. 40-08-82-12-11