Other first to be the

.fer supply section .(vision of water resources 89 Kings Highway OVER, DELAWARE 19901 .'HONE: 302-739-3665 FAX: 302-739-2296

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

FORMATION LOG

Pd52-09

PAGE _____ OF ____ PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED			
ERMIT# 183875-W LOCAL ID#			
PROPERTY OWNER Roland Fleetwood			
WELL CONTRACTOR AMERICAN Water Well Systems, Inc. LIC# 608 DESCRIPTION TOP OF STRATA BOTTOM OF			
DESCRIPTION		TOP OF STRATA	BOTTOM OF STRATA
Top soil		0	1
Tan day		1	15
Tan fine to med.		15	38
Gray and brown day		<i>3</i> 8	65
White fine to med sand	,	<i>4</i> 5	90
White fine to med sand Tan fine to coarse		90	130
, , , , , , , , , , , , , , , , , , ,			
		,,	
OTHER COMMENTS:			
<i>y</i>		RECEIVED	
		SEP 2 7 2002	
	w	ATER SUPPLY	
I HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT			
Signature of Well Driller In Charge	License#	Date	5/04