MAIL TO:
WATER SUPPLY BRANCH
DIVISION OF WATER RESOURCES
P.O. BOX 1401
DOVER, DELAWARE 19903

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED 30 DAYS AFTER CONSTRUCTION DATE

MONITOR WELL COMPLETION REPORT

PLEASE PRINT OR TYPE	
PERMIT NO	IS COMPLETED WELL LOCATED AS SHOWN ON
Owner Sty Eng.	APPLICATION FORM? YES[] NO[X]
Address 4/00	IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.
1/20 / - / 60	Moved 145 W 6
Telephone Number 75/24/58	
Consulting Firm/Supervising Geologist (If applicable)	95' N
Telephone Number 451-2467	
Well Contractor 260	•
Date of Completion 5/15/89	
4 /	· · · · · · · · · · · · · · · · · · ·
Drilling Method:	
	·
WELL CONSTRUCTION	De 32-23
Total depth drilled:	Will Pede 22
Depth to water 7.5	DRILLERS LOG DESCRIP. TOP OF STRATA BOTTOM
Surveyed Top of Casing Elevations	BROWN SANDY TOPSOIL O 10
Inner Outer Ft. above Sea Level	,
CASING SEQUENCE	BRANGE-BROWN M 1.0 4.0
Inner casing Outer casing	SAMS U/ TR CLAY
Casing top	
Casing bottom 72.7	
1 1 1 1 1 1	GLAVA BROWN MOD 4.0 155
Casing diameter / 25	F-MSAKDY CLAD
Casing material PV	
SCREEN SEQUENCE	
Inner casing Outer casing	LRAY N-CSANI)
Screen top	1/TH CIOX 8.5
Screen bottom	777
Screen diameter /. 2.5	
Screen material	
Type of Grout 850 from to 15	
Gravel pack interval from to	
Aquifer/Formation screened in: COLUMBIA	
riquiter Formation screened in.	
[////	
Samples Logged By: // DALLAD 5	
Samples Logged By: (Name)	
1.1/h// 61 11/2	
211/4. Reh 1165	
(Title) (Company)	
\sim	
1	
Well Drilled By: (Company Name)	
(company Name)	4
1 / 0 / 1/2/// 1 / /./~ 1	SUPPLEMENTAL DRILLERS LOG ATTACHED?
1 / March Doundo 6/6/89	YES[] NO >
(Signature of Driller in Charge) (Date)	PAGE 1 OF PAGES
	TAGE FOR TAGES