

M3A-26

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

BORING NO. CH1

CONTRACT: 24-112-09 S.R. 24 - MAINLINE IMPROVEMENT - BOAT YARD SITE

BORING LOCATION:

PROGRESS NO.	DAILY SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
02/09/05 1	0.5'	2	Wet loose brown silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	6" Topsoil
	2.0'	3			
20" Recovery					
2	2.0'	3	Wet loose brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	
	4.0'	4			
	5	5			
22" Recovery					
3	4.0'	3	Moist loose brown fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
	6.0'	4			
		5			
16" Recovery					
4	6.0'	3	Wet loose brown fine to coarse sand w/some silt, trace of gravel.	A-2-4 (0)	Water @ 7.0'
	8.0'	6			
		9			
22" Recovery					
5	8.0'	4	Saturated loose brown silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	
	10.0'	4			
		5			
		5			
22" Recovery					
6	13.0'	5	Wet medium dense brown coarse to fine sand w/some gravel, trace of silt.	A-1-b (0)	
		5			
		7			
	15.0'	7			

(END)

BORING NO. CH1
SURFACE ELEV.