

PH3427

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

BORING NO. C#2

CONTRACT: 24-112-09 S.R.24 - MAINLINE IMPROVEMENT - BOAT YARD SITE
BORING LOCATION:

DAILY	SAMPLE	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
02/09/05	1	0.6'	2	Wet very loose brown fine to coarse sand	A-2-4 (0)	7" Topsoil
		2.0'	2	w/some silt, trace of gravel.		
		2.0'	2			
21" Recovery						
	2	2.0'	3	Wet loose brown silty fine to coarse sand	A-2-4 (0)	
			3	w/trace of gravel.		
			3			
		4.0'	4			
20" Recovery						
	3	4.0'	4	Moist medium dense brown fine to coarse	A-3 (0)	
			6	sand w/trace of silt and gravel.		
			7			
		6.0'	5			
20" Recovery						
	4	6.0'	7	Wet medium dense brown fine to coarse sand	A-3 (0)	Water @ 6.5'
			5	w/some gravel, trace of silt.		
			10			
		8.0'	9			
24" Recovery						
	5	8.0'	8	Wet medium dense brown fine to coarse sand	A-2-4 (0)	
			7	w/some silt, trace of gravel.		
			6			
		10.0'	5			
20" Recovery						
	6	13.0'	4	Saturated loose brown coarse to fine sand	A-1-b (0)	
			5	w/some gravel and silt.		
			5			
		15.0'	2			
20" Recovery						
(END)						

BORING NO. C#2
SURFACE ELEV.