

M34-20

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

BORING NO. C#3

CONTRACT: 24-112-09 S.R.24 - MAINLINE IMPROVEMENT - BOAT YARD SITE
BORING LOCATION:

DAILY PROGRESS NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
02/09/05 1	0.7'	2	Wet loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	8" Topsoil
	2.0'	3			
		3			
22" Recovery					
2	2.0'	2	Wet very loose brown silty fine sand w/trace of coarse sand and gravel.	A-2-4 (0)	
		2			
		2			
	4.0'	2			
20" Recovery					
3	4.0'	4	Wet medium dense brown fine sand w/some silt and gravel.	A-2-4 (0)	
		6			
		7			
	6.0'	7			
16" Recovery					
4	6.0'	6	Wet medium dense brown coarse to fine sand w/some silt, trace of gravel.	A-2-4 (0)	Water @ 7.5'
		7			
		8			
	8.0'	7			
22" Recovery					
5	8.0'	9	Wet medium dense brown silty fine to coarse sand w/trace of gravel.	A-2-4 (0)	
		12			
		7			
	10.0'	6			
20" Recovery					
6	13.0'	2	Saturated very loose brown fine sand w/some silt, trace of coarse sand.	A-2-4 (0)	
		1			
		2			
	15.0'	2			
22" Recovery					
(END)					

BORING NO. C#3
SURFACE ELEV.