

PH43-08

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

BORING NO. RP#1

CONTRACT: 24-112-09 S.R.24 - MAINLINE IMPROVEMENT - RIVERSIDE PLAZA - MUSEUM SITE

BORING LOCATION:

DAILY PROGRESS NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
02/08/05 1	0.6'	4	Wet loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	6" Topsoil
	2.0'	4			
18" Recovery					
2	2.0'	3	Wet loose brown fine sand w/some silt and coarse sand.	A-2-4 (0)	
		3			
		3			
	4.0'	2			
15" Recovery					
3	4.0'	2	Saturated loose brown fine sand w/some silt, trace of coarse sand and gravel.	A-2-4 (0)	Water @ 5.3'
		2			
		3			
	6.0'	3			
16" Recovery					
4	6.0'	3	Saturated loose brown fine sand w/some silt, trace of coarse sand.	A-2-4 (0)	
		3			
		3			
	8.0'	4			
18" Recovery					
5	8.0'	4	Saturated loose brown fine sand w/some silt and coarse sand, trace of gravel.	A-2-4 (0)	
		4			
		5			
	10.0'	6			
22" Recovery					
6	13.0'	3	Saturated loose brown fine to coarse sand w/trace of silt and gravel.	A-2-4 (0)	
		3			
		4			
	15.0'	5			
22" Recovery					
(END)					

BORING NO. RP#1
SURFACE ELEV.