

PH43-10

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

BORING NO. RP#3

CONTRACT: 24-112-09 S.R.24 - MAINLINE IMPROVEMENTS - RIVERSIDE PLAZA - MUSEUM SITE

BORING LOCATION:

DAILY PROGRESS NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
02/07/05 1	0.6'	2	Moist very loose brown fine to coarse sand	A-2-4 (0)	7" Topsoil
	2.0'	2	w/some silt, trace of gravel.		
		2			
23" Recovery					
2	2.0'	2	Wet very loose brown fine to coarse sand	A-2-4 (0)	Water @ 4.0'
		2	w/some silt and gravel.		
		2			
	4.0'	2			
20" Recovery					
3	4.0'	1	Saturated very loose brown silty fine sand	A-2-4 (0)	
		1	w/some coarse sand, trace of gravel.		
		W/H			
	6.0'	1			
18" Recovery					
4	6.0'	3	Saturated loose brown fine to coarse sand	A-2-4 (0)	
		3	w/some silt, trace of gravel.		
		3			
	8.0'	6			
20" Recovery					
5	8.0'	3	Saturated loose brown fine sand w/some	A-2-4 (0)	
		3	coarse sand and silt, trace of gravel.		
		3			
	10.0'	5			
22" Recovery					
6	13.0'	4	Saturated loose brown fine sand w/some	A-2-4 (0)	
		4	coarse sand and silt, trace of gravel.		
		4			
	15.0'	6			

(END)