

PH43-12

STATE OF DELAWARE  
DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS

TRACT: 24-112-09 S.R.24 - MAINLINE IMPROVEMENTS - RIVERSIDE PLAZA - MUSEUM SITE  
BORING LOCATION:

BORING NO. RP#5

PROGRESS NO.	DAILY	SAMPLE	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
02/07/05 1			0.6'	3	Wet loose brown silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	7" Topsoil
			2.0'	4			
				5			
23" Recovery							
2			2.0'	2	Saturated loose brown silty fine sand	A-2-4 (0)	
3				3	w/some coarse sand, trace of gravel.		
			4.0'	5			
20" Recovery							
3			4.0'	1	Saturated very loose brown silty fine sand	A-2-4 (0)	Water @ 5.5'
				1	w/trace of coarse sand and gravel.		
			6.0'	1			
14" Recovery							
4			6.0'	2	Saturated very loose brown fine sand	A-2-4 (0)	
				2	w/some silt, trace of coarse sand.		
			8.0'	2			
18" Recovery							
5			8.0'	4	Saturated loose brown fine sand w/some silt, A-2-4 (0)		
				3	trace of coarse sand.		
			10.0'	3			
				4			
18" Recovery							
6			13.0'	3	Saturated loose brown coarse to fine sand	A-3 (0)	
				3	w/trace of silt and gravel.		
				5			
			15.0'	8			
20" Recovery							
( END )							

BORING NO. RP#5  
SURFACE ELEV.