

JUN 30 1976

STATE OF DELAWARE
WATER AND AIR RESOURCES COMMISSION
Water Resources Division
Dover, Delaware 19901

WRC-2
7/69

MAP OF DELAWARE
WATER RESOURCES SECTION

WELL COMPLETION REPORT

1. Well Number: Qc13-11
Owner of Well: Harold S. Cota

8. Well Head Completion:
NA Pitless Adapter _____ Type _____
_____ inches above grade

2. Test Well:
Observation Well _____
Production Well
Well Abandoned? Yes _____ No _____

9. Static Water Level:
_____ feet below grade
_____ feet above grade

3. Total Well Depth: 34 feet
Date Completed: 6-7-76

10. Pumping Water Level:
_____ feet below grade after
_____ hour/s at _____ GPM

4. Grouts Type: cement
from _____ foot to _____ foot
from _____ foot to _____ foot

11. Permanent Pump Installed?
Yes _____ No
a. Shallow Well _____
Deep Well _____
b. Reciprocating _____ Rotary _____
Centrifugal _____ Jet _____
Submersible _____
c. Capacity _____ GPM

5. Casings Type: PVC
_____ inches to _____ foot
_____ inches to _____ foot
Drive Shaft Yes _____ No

12. Well Number
(Leave Blank)

6. Screen Settings:
27 feet to 34 feet

7. Gravel Packed? Yes No _____
27 feet to 34 feet

Qc13-11

13. Well Log

Formation	Thickness of Stratum	Depth to Bottom of Stratum
top soil	0	1
fine sand: fine	1	2
fine sand: med	10	12
fine sandy clay	12	17
medium sand: med	17	21
dk. tan sand: med coarse	21	34

14. Signature of Owner/Well Contractor: Harold S. Cota Date: _____

10-06-78 205/10