..L TO:

WATER SUPPLY SECTION
DIVISION OF WATER RESOURCES
P.O. BOX 1401, 89 KINGS HIGHWAY
DOVER, DELAWARE 19903
PHONE: 302-739-3665
FAX: 302-739-2296

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

FORMATION LOG

Qd24-04

PAGE _____ OF _____ PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED

PERMIT# 162643 | LOCAL ID#

PROPERTY OWNER Cecilia B. Lowe

WELL CONTRACTOR Ben Wood | LIC# 778

DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
Top Soil	0	2
Tan Sand	Tbd 2	40
Fine Gray Sand	40	85
Coarse Tan & White Sand	Tb+ 85	130

OTHER COMMENTS:

I HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT

Ben Wood — Signature of Well Driller In Charge | 778 — License# | 2/18/99 — Date

White - DNREC • *Canary - Contractor* • *Pink - Owner*

Doc. No. 40-08-82-12-11