AIL TO:

WATER SUPPLY SECTION
DIVISION OF WATER RESOURCES
89 KINGS HIGHWAY
DOVER, DELAWARE 19901
PHONE: 302-739-9944
FAX: 302-739-7764

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

FORMATION LOG

Qd42-03

PAGE 1 OF _____ PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED

PERMIT# 220374	LOCAL ID#
PROPERTY OWNER SCARBOROUGH	
WELL CONTRACTOR Meyer	LIC# 319

DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
Top Soil	0	1
clay	1	5
coarse Sand	5	60
Stones	60	70
med Sand	70	165
Clay	165	168
Fine Brown Sand	168	180
clay & Silt	180	200

OTHER COMMENTS: The First Hole was Abandoned @ 70' Due To Pneumatic Hose & Stone. After 15 minutes of Down pressure Rods were pulled and the Bit was Disconnected. We moved 5 feet and Successfully completed the Three Bores to 200'

I HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT

Signature of Well Driller In Charge | License# 419 | Date 8/6/07

White - DNREC • Canary - Contractor • Pink - Owner

Doc. No. 40-08-82-12-11