...TER SUPPLY SECTION
...VISION OF WATER RESOURCES
89 KINGS HIGHWAY
DOVER, DELAWARE 19901
PHONE: 302-739-3665
FAX: 302-739-2296

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

FORMATION LOG

QF31-07

PAGE _____ OF _____ PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED

PERMIT# 181144-W | LOCAL ID# 2-32-21-6.19

PROPERTY OWNER DHANPAUL DACHUKANDAN

WELL CONTRACTOR PENGLISH | LIC# 282

DESCRIPTION	TOP OF STRATA	BOTTOM OF STRATA
TOPSOIL	0	1
SAND & CLAY	1	6
WHITE SAND GRAVEL	6	35
TAN SAND GRAVEL	35	65

OTHER COMMENTS:

RECEIVED
DEC 03 2002
WATER SUPPLY

HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT

Signature of Well Driller In Charge: Peyton English | License#: 282 | Date: 11/21/01

White - DNREC • Canary - Contractor • Pink - Owner

Doc. No. 40-08-82-12-11