MAIL TO:
WATER SUPPLY BRANCH
DIVISION OF WATER RESOURCES
P.O. BOX 1401
DOVER, DELAWARE 19903

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS AFTER CONSTRUCTION DATE.

MONITOR WELL COMPLETION REPORT

Q914-70 15 V PKB

PLEASE PRINT OR TYPE

PERMIT NO. 7740 LOCAL ID (14) W27A
Owner NCR MILLSBORO
Address 499 MITCHELL STREET
City MILLSBORO State DE Zip 19966
Telephone Number 703-821-3700
Consulting Firm/Supervising Geologist (If applicable)
ENVIRONMENTAL STRAT. CORP/DAVE KINDIG
Telephone Number 703-821-3700
Well Contractor DELMARVA Drilling Co.
Date of Completion 3/9/89
Name of DNREC Contact Person DIANE WEHNER
Drilling Method MUD rotary

WELL CONSTRUCTION

Total depth drilled: 28'
Depth to water 8'
Surveyed Top of Casing Elevations
N/A (Inner) N/A (Outer) Ft. above Sea Level

CASING SEQUENCE

	Inner casing	Outer casing
Casing top	2'	
Casing bottom	18'	
Casing diameter	4"	
Casing material	PVC	

SCREEN SEQUENCE

	Inner casing	Outer casing
Screen top	18'	
Screen bottom	28'	
Screen diameter	4"	
Screen material	PVC	

Type of Grout CEMENT from 0 to 16
Gravel pack interval from 28 to 16
Aquifer/Formation screened in: COLUMBIA
Type of samples (ditch, split spoon, etc.)
SPLIT SPOON

Samples Logged By: LISA Bryda (Name)
GEOLOGIST (Title) ENVIRON. STRATEGIES (Company)
Well Drilled By: DELMARVA Drilling Co. (Company Name)
Brad Hartman 3/9/89 (Signature of Driller in Charge) (Date)

IS COMPLETED WELL LOCATED AS SHOWN ON APPLICATION FORM? YES [V] NO [ ]
IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.

RECEIVED
MAR 20 1989

DRILLERS LOG DESCRIP.	TOP OF STRATA	BOTTOM
TOP SOIL	0	2
SAND	2	5
CLAY	5	7
SAND	7	10
SAND	10	20
SAND	20	28

SUPPLEMENTAL DRILLERS LOG ATTACHED?
YES [ ] NO [V]
PAGE 1 OF 1 PAGES

White - Water Supply • Canary - Other • Pink - Owner • Goldenrod - Contractor

Doc. No. 40-08/88/05/03