

MAIL TO:
 WATER SUPPLY BRANCH
 DIVISION OF WATER RESOURCES
 P.O. BOX 1401
 DOVER, DELAWARE 19903

STATE OF DELAWARE
 DEPARTMENT OF NATURAL RESOURCES
 AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST
 BE RETURNED WITHIN 30 DAYS
 AFTER CONSTRUCTION DATE.

MONITOR WELL COMPLETION REPORT

0914-72

PLEASE PRINT OR TYPE

PERMIT NO. 77677 LOCAL ID W228A
 Owner KICK MILLSBORO
 Address 499 MARSHALL ST.
 City MILLSBORO State DE Zip 19966
 Telephone Number 703-831-3700
 Consulting Firm/Supervising Geologist (if applicable)
ENVIRONMENTAL GREAT CAP/D KINDIG
 Telephone Number 703-831-3700
 Well Contractor DELMARVA DRILLING
 Date of Completion 3/10/89
 Name of DNREC Contact Person DIANE WETTER
 Drilling Method MWD ROTARY

WELL CONSTRUCTION

Total depth drilled: 28'
 Depth to water: 28'
 Surveyed Top of Casing Elevations
N/A ^{Feet} N/A ^{Feet} above Sea Level
Other

CASING SEQUENCE

Inner casing	Outer casing
<u>2'</u>	
<u>18'</u>	
<u>4"</u>	
<u>PVC</u>	

SCREEN SEQUENCE

Inner casing	Outer casing
<u>18'</u>	
<u>28'</u>	
<u>4"</u>	
<u>PVC</u>	

Type of Grout CEMENT from 16 to 0
 Gravel pack interval from 28 to 16
 Aquifer/Formation screened in: CAULIMBIA
 Type of samples (ditch, split spoon, etc.)
SPLIT SPOON

Samples Logged By: LISA BRYDA
(Name)
GEEDECAT/ENVIRONMENTAL STRAT CORP
(Company)

Well Drilled By: DELMARVA Drilling Co.
(Company Name)

D. Bryant 3/10/89
(Signature) (Date)

IS COMPLETED WELL LOCATED AS SHOWN ON
 APPLICATION FORM? YES [] NO []
 IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.

FIELD
 MAR 20 1989
 WATER SUPPLY

DRILLERS LOG DESCRIP.	TOP OF STRATA	BOTTOM
<u>TOP SOIL</u>	<u>0</u>	<u>2</u>
<u>SAND</u>	<u>7</u>	<u>10</u>
<u>CLAY</u>	<u>10</u>	<u>15</u>
<u>SAND</u>	<u>15</u>	<u>17</u>
<u>SAND</u>	<u>17</u>	<u>20</u>
	<u>20</u>	<u>28</u>

SUPPLEMENTAL DRILLERS LOG ATTACHED?
 YES [] NO []
 PAGE 1 OF 1 PAGES