MAIL TO: WATER SUPPLY BRANCH DIVISION OF WATER RESOURCES P.O. BOX 1401 DOVER, DELAWARE 19903

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS AFTER CONSTRUCTION DATE.

MONITOR / OBSERVATION WELL COMPLETION REPORT

PLEASE PRINT OR TYPE	<u> </u>				
PERMIT NO. 103539 LOCAL ID MCS 2			IS COMPLETED WELL LOCATED AS SHOWN ON APPLICATION FORM? YES [-"] NO [] IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.		
Owner DNIV OF DEL					
Address, City State _DE _ Zip 19716			LAT 3832 25		
Telephone Number 831-2833			!		
Consulting Firm/Supervising Geologist (If applicable)			LON 75 18 47		
DGS / AS AUDRES			Qg 32-08		
Telephone Number			[
Well Contractor D65					
Date of Completion 4.20.95					
Name of DNREC Contact Person 3, Van AS 5					
Drilling Method					
WELL CONSTRUCTION					
Total depth drilled: 45					
Depth to water 6.34			DRILLERS LOG DESCRIP.	TOP OF STRATA	BOTTOM
Surveyed Top of (
Ft. above Sea Level			See 103512		
Inner Outer					
	0401110	NEGUENOE	1		
		SEQUENCE		-	
1	Inner casing	Outer casing			
Casing top	10		,		
Casing bottom	· · · · · · · · · · · · · · · · · · ·				
Casing diameter	2				
Casing material	P/C	l			
SCREEN SEQUENCE					
	Inner casing	Outer casing			
Screen top	10				
Screen bottom	13				
Screen diameter	2 PVC				
Screen material l	- PVC				
	3 π κέψ	A 75			
Type of Grout 36 NT from 0 to 7.5					
Gravel pack interval fromto			-		
Aquifer/Formation screened in:					
Type of samples (ditch, split spoon, etc.)					
ALUER FLITE					ļ
Samples Logged By: A S A S A S A S A S A S A S A S A S A			·		i
(Title) (Company)					
Well Drilled By: D65				<u> </u>	
(Company Name)			l 		
I PARAZA A I					
(Signature of Driller in Charge) (Doznako 5/8/95 (Date)			SUPPLEMENTAL DRILLERS LOG ATTACHED? YES[] NO[]		