

MAIL TO:
 WATER SUPPLY BRANCH
 DIVISION OF WATER RESOURCES
 P.O. BOX 1401
 DOVER, DELAWARE 19903

STATE OF DELAWARE
 DEPARTMENT OF NATURAL RESOURCES
 AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST
 BE RETURNED WITHIN 30 DAYS
 AFTER CONSTRUCTION DATE.

MONITOR / OBSERVATION WELL COMPLETION REPORT

PLEASE PRINT OR TYPE

PERMIT NO. 103814 LOCAL ID 05B3
 Owner Allen's Hatchery, INC.
 Address 126 W Shipton St
 City Seaford State De. Zip 19973
 Telephone Number 302-629-9163
 Consulting Firm/Supervising Geologist (If applicable)
N/A

IS COMPLETED WELL LOCATED AS SHOWN ON
 APPLICATION FORM? YES [] NO []
 IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.

Telephone Number _____
 Well Contractor Daisey's Well Drilling
 Date of Completion 6-9-95
 Name of DNREC Contact Person Bruce Bagley
 Drilling Method Auger

WELL CONSTRUCTION

Total depth drilled: 5'
 Depth to water 6"
 Surveyed Top of Casing Elevations
 Inner 2 Outer _____ Ft. above Sea Level

CASING SEQUENCE

	Inner casing	Outer casing
Casing top	<u>2 1/4"</u>	
Casing bottom	<u>3'</u>	
Casing diameter	<u>2"</u>	
Casing material	<u>PVC</u>	

SCREEN SEQUENCE

	Inner casing	Outer casing
Screen top	<u>3'</u>	
Screen bottom	<u>5'</u>	
Screen diameter	<u>2"</u>	
Screen material	<u>PVC</u>	

Type of Grout Ortonite Hole plug from 0' to 3'
 Gravel pack interval from 3' to 5'
 Aquifer/Formation screened in: Sand
 Type of samples (ditch, split spoon, etc.) _____

Samples Logged By: _____ (Name)

(Title)

(Company)

Well Drilled By: Daisey's Well Drilling
 (Company Name)

Michael E. Daisey 6-9-95
 (Signature of Driller in Charge) (Date)

Qy34-23

DRILLERS LOG DESCRIPT.	TOP OF STRATA	BOTTOM
<u>Top Soil</u>	<u>0'</u>	<u>3'</u>
<u>yellow Sand</u>	<u>3'</u>	<u>5'</u>

SUPPLEMENTAL DRILLERS LOG ATTACHED?
 YES [] NO []
 PAGE 1 OF _____ PAGES