MAIL TO: WATER SUPPLY BRANCH DIVISION OF WATER RESOURCES P.O. BOX 1401 DOVER, DELAWARE 19903

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST
/BE RETURNED WITHIN 30 DAYS
AFTER CONSTRUCTION DATE.

MONITOR / OBSERVATION WELL COMPLETION REPORT

PLEASE PRINT OR TYPE	
PERMIT NO. 103815 LOCAL ID 058 4"	is completed well located as shown on
Owner Hilen's Hatchery, INC	APPLICATION FORM? YES[4] NO[]
Address 126 N Shipley St.	IF NO. DESCRIBE LOCATION CHANGE OR OTHER COMMENTS
City Seaford State De Zip 19973	_ /
Telephone Number	
Consulting Firm/Supervising Geologist (If applicable)	
Telephone Number	_ /
Well Contractor Caisey's Well Orilling	- (
Date of Completion 6-9-95	
Name of DNREC Contact Person Bruce Bagles	-
Drilling Method Huger	-
	_
WELL CONSTRUCTION	()a34-24
Total depth drilled:	
Depth to water6"	DRILLERS LOG DESCRIP. TOP OF STRATA BOTTOM
Surveyed Top of Casing Elevations	Top 5011 0' 3'
Inner Outer Ft. above Sea Level	- 'Sand 3' 5'
CASING SEQUENCE	
inner casing Outer casing	
Casing top 34"	11.5
Casing bottom	
Casing diameter 3"	
Casing material PVC	
SCREEN SEQUENCE	
Inner casing Outer casing	
Screen top	
Screen bottom	
Screen diameter Screen material	
Screen material EVC	
Type of Grout Bestonite Hole from O' to 3'	
Gravel pack interval from 3' to 5'	
Aquifer/Formation screened in: 5 and	
Type of samples (ditch, split spoon, etc.)	
Samples Logged By: (Name)	
(D. L.)	
(Title) (Company)	
_	
Well Drilled By: Loisen's Well Drilling	1
(Company Name)	
Well Drilled By: Daisey's well Drilling (Company Name) Michael C. Daisey 6-9.95	CUDDI EMENTAL DOLL EDGI OG ARTINGEN
Muchoul C. Daison 1-9.05	SUPPLEMENTAL DRILLERS LOG ATTACHED? YES[] NO[47
(Signature of Driller in Charge) (Date	PAGE LOF PAGES
	1