DELAWARE GEOLOGICAL SURVEY

UNIVERSITY OF DELAWARE NEWARK, DELAWARE , 3

Qh 33-2

WELL COMPLETION REPORT

PLEASE SUBMIT THIS REPORT WITHIN 30 DAYS AFTER COMPLETION OF THE WELL

| WELL LOG | Casing and screen record | | | Owner Hail Bennett |
|---|--------------------------|----------|---|---|
| State the kind of formations penetrated, their depth, their thickness, and if water-bearing | screen and other ac | cessorie | of casing, liner, shoe, es (if no casing used, | Address Frankford Dil |
| 9 h 33-2 (40) elev, 22' e | give diameter of well | Dlam. | Feet | Man Omar |
| Spool From O To 8 | | ins. | From To | |
| Very fine crange 8"-4 | Casing | 4 | 0-55 | Tenant |
| Sand | J | ' | | Address |
| Eine white sand with 4-14 | 8- #20 slot | | 55-63 | (Please draw location of well and road |
| brown worm strucks | | | | sketch on reverse side) |
| light grow sandy 14-23 | Cook www red | | | PUMPING TEST |
| Clay 23-30 | Bass straine | | | Hours Pumped 8 Pumping rate 20 GPM |
| ruff colored clonery | | | | WATER LEVEL |
| sand and some | | | | Distance from land surface to water: |
| graveland wood | | | | Before Pumpingft. |
| (small broushes) | · | | | After Pumping 30 est, ft. |
| vine savary day | | | | APPEARANCE OF WATER Clear |
| of clayey sold | | | | Cloudy |
| Very fine to very 39-43 | | | | Taste |
| Evarse silly | | | | Odor |
| yellow sand. | | | | Height of casing above land surface ft. |
| Fine white sand 43-48 | | | | DUMP |
| and selt and | | | | TypeCWVVYGUGASCapacity—GPM |
| large gravel. | | | | GPHr |
| Fairly course orange 48-50 | | | | Pump column length ft. |
| colored sand with | | | | REMARKS |
| considerable self. | | | | |
| Time and very line 50-53 | | | | • |
| white sand and | | | | |
| siet. | | | · | |
| and gravel-fine and down. | | | ا ي | |
| and newl-line | | | (3). \ | |
| and down. | | | | ø |
| source, | | V0.7 | | Date well completed Light 15, 1953 |
| | (6) | ار کا | (,9) | Well Driller # 1/8 |
| | | | | WHITE |
| · | | | | Signature |