

MAIL TO:

WATER SUPPLY SECTION
DIVISION OF WATER RESOURCES
89 KINGS HIGHWAY
DOVER, DELAWARE 19901
PHONE: 302-739-3665
FAX: 302-739-2296

STATE OF DELAWARE
DEPARTMENT OF NATURAL RESOURCES
AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST
BE RETURNED WITHIN 30 DAYS OF
CONSTRUCTION DATE

FORMATION LOG

Q:13-08

PAGE 1 OF 1 PAGES

PLEASE PRINT OR TYPE - ILLEGIBLE OR INCOMPLETE FORMS WILL BE RETURNED

PERMIT# 205148 LOCAL ID# 30 Q:13-08

PROPERTY OWNER DOT Sussex

WELL CONTRACTOR DGS LIC# 999

| DESCRIPTION | TOP OF STRATA | BOTTOM OF STRATA |
|--|---------------|------------------|
| Fill | 0 | 6" |
| reddish-orange fine sand | 6" | 1.5' |
| yellow-brown fine sand and silt | 1.5' | 3' |
| pale gray-white silt with stringers of orange fine sand | 3 | 6' |
| gray-steel blue clay with stringers of orange fine sand | 6 | 9' |
| white clayey fine sand, cleans up ~34' to a | 9 | 94' |
| yellow-gray fine-medium sand with widely scattered thin (<1') white silt beds (84-87' gravelly zone) | | |
| olive gray fine-medium sand with scattered thin (<1'-3') brown-orange-gray clay beds, becomes yellow and coarse-very coarse between 150-172' | 94 | 172' |
| gray-orange fine sandy clay (172-176') to silty fine sand (176-187') | 172 | 187' |
| GAMMA LOG shows very clean sand; medium gravel stuck between auger bolts and flights, cuttings showed very coarse sand and fine gravel, but no good sample | 187 | 219' |

OTHER COMMENTS: was recovered

34 (25)

HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS ACCURATE AND CORRECT
Signature of Well Driller In Charge [Signature] License# 686 Date 11/19/04