



STATE OF DELAWARE
WATER RESOURCES SECTION

STATE OF DELAWARE
WATER AND AIR RESOURCES COMMISSION
Water Resources Division
Dover, Delaware 19901

RECEIVED

MAY 28 1976

WRD-2
7/69

Q1345

WELL COMPLETION REPORT

DELAWARE GEOLOGICAL
SURVEY

1. Permit Number: 55723
 Owner of Well: Banka Development, Inc.

2. Test Well _____
 Observation Well _____
 Production Well
 Well Abandoned? Yes _____ No _____

3. Total Well Depth 60 feet
 Date Completed 5-18-76

4. Grout: Type Cement
 from 3 feet to 15 feet
 from _____ feet to _____ feet

5. Casing: Type PVC
0 inches to 55 feet
 _____ inches to _____ feet
 Drive Shoe? Yes _____ No

6. Screen Setting:
55 feet to 60 feet

7. Gravel Packed? Yes No _____
52 feet to 60 feet

8. Well Head Completion:
110 Pitless Adapter _____ Type _____
 _____ inches above grade

9. Static Water Level:
6 feet below grade
 _____ feet above grade

10. Pumping Water Level:
18 feet below grade after
1 hour at 75 GPM

11. Permanent Pump Installed?
 Yes _____ No
 a. Shallow Well _____
 Deep Well _____
 b. Reciprocating _____ Rotary _____
 Centrifugal _____ Jet _____
 Submersible _____
 c. Capacity _____ GPM

12. Well Number _____
 (Leave Blank)

location map on back

13. Well Log

Formation	Thickness of Stratum	Depth to Bottom of Stratum
<u>Brown clay</u>	<u>0</u>	<u>5</u>
<u>Brown sand - med</u>	<u>5</u>	<u>15</u>
<u>Brown musky clay</u>	<u>15</u>	<u>30</u>
<u>15 Tan sand - med</u>	<u>30</u>	<u>50</u>
<u>15 Tan sand - med coarse</u>	<u>50</u>	<u>60</u>

14. Signature of Water Well Contractor _____ Date _____

Idene Well Drilling

5-20-76