

No. 2 Application No. 03043E
 Drilled 05-17-86 County Sussex Use monitor
 Location NW corner of US 1 and York Rd., South Bethany, Delaware
 Drilled by Service Oil Co. Address PO Box 279, Milford, Del. 19963
 Logging Method Air Rotary Sampling Method cuttings
 Diameter 7" Total Depth 11'
 Type PVC (no glue) Diameter 4" Length .5'
 Casing Type PVC (no glue) Slot 20 Diameter 4" Length 10.5'
 Sealant none Casing Seal cement
 Static Water Level 3.89' BTCC Geologic Formation Sand

DEPTH FROM FACE	SAMPLE NUMBER	BLOWS PER 6" CN SAMPLER	WELL DESIGN	IDENTIFICATION OF SOILS/REMARKS
5'			well screen	65045 Gravel and asphalt and sand fill
1'				tan 1-3. mod. sorted, subrounded quartz SAND.
				White to gray, medium, very well sorted, sub- rounded, quartz SAND.
9'				Black organic peaty CLAY. Some fine sized fiber. Sample is plastic (roles to 1/16" wire)
1'				Note: all wells completed below grade in a manhole with seal and locking cap.
			Log by s. Boyes	
			Qj 52-50	