## MAIL TO:

FAX: 302-739-2296

WATER SUPPLY SECTION DIVISION OF WATER RESOURCES 89 KINGS HIGHWAY DOVER, DELAWARE 19901 PHONE: 302-739-3665

## STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS OF CONSTRUCTION DATE

## **FORMATION LOG**

Rc23-05

**PAGES** PAGE \_\_\_\_\_ OF \_\_\_\_

// i //	~~	<b>n</b>	L-1-00	
HEREBY AFFIRM THE INFORMATION I HAVE SUBMITTED IS	ACCURATE AND CO	RRECT		
<u>*</u>			end okak da Bul	
OTHER COMMENTS:				
			· · · · · · · · · · · · · · · · · · ·	
Coarse Tan Sand		40	78	
Clay Sand & Shell? Coarse Tan Sund		12	12 40 78	
Clay		0	12	
DESCRIPTION		TOP OF STRATA	BOTTOM OF STRATA	
roperty owner RWL (Bailey Job)  vell contractor Ben Wasa  description		LIC# 778		
ROPERTY OWNER RWL (Bailey	Job)			
ERMIT# 172175	LOCAL ID#			