MAIL TO: WATER SUPPLY BRANCH DIVISION OF WATER RESOURCES P.O. BOX 1401 DOVER, DELAWARE 19903

STATE OF DELAWARE DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT MUST BE RETURNED WITHIN 30 DAYS AFTER CONSTRUCTION DATE.

MONITOR / OBSERVATION WELL COMPLETION REPORT

PLEASE PRINT OR TYPE Kd 15-09	
PERMIT NO. 99103 LOCAL ID	IS COMPLETED WELL LOCATED AS SHOWN ON
Owner D+ J Inc	APPLICATION FORM? YES NO[]
Address 315 River Vista Dr.	IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENTS.
City Seaford State De Zip 19978	The state of the s
Telephone Number 629-669	
Consulting Firm/Supervising Geologist (If applicable)	- Constitution of the Cons
Telephone Number	The second secon
Well Contractor BUCUS Inc	
Date of Completion	JUN 2 7 199
Name of DNREC Contact Person	T /
Drilling Method	Water Barrier
	Sept. Company of the
WELL CONSTRUCTION	
Total depth drilled:	_ /
Depth to water	DRILLERS LOG DESCRIP. TOP OF STRATA BOTTOM
Surveyed Top of Casing Elevations	
Inner Outer Ft. above Sea Level	FRUETAN SAM DI 21
Tuner Outer	/ Yellow clay 21 31
CASING SEQUENCE	FINE TON SNM 21 171
Casing top Inner casing Outer casing	
Casing bottom 2 Below 2 Bolow	
Casing diameter 2' 4'	
Casing material Puc Steel	
Cosing material	
SCREEN SEQUENCE	
inner casing Outer casing	
Screen top Screen bottom	
Screen diameter 2'	
Screen material	
Pentonito / 2	
Type of Grout Come from 0' to 1'	
Gravel pack interval from 2' to 17'	
Aquifer/Formation screened in: Surface	
Type of samples (ditch, split spoon, etc.)	
2) pe de dampies (ander, spire spoon, etc.)	
Samples Logged By:	
(Name)	
ن	
(Title) (Company)	
$Q_{i,a,a}$	
Vell Drilled By: UK/VS TIME	
(Company Nante)	
Vell Drilled By: Surv S (Company Name)	CHIDDI PMENEAL DRILL BROLLOG ARMA CANADA
a comer III Wall II borday	SUPPLEMENTAL DRILLERS LOG ATTACHED? YES[] NO[]
(Signature of Driller in Charge) (Date)	
	PAGE 1 OF PAGES