

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. S # 2

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
BORING LOCATION: STA. 1010+19, 35.3' Lt. CENTERLINE

R124-52

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
	1	1.0' 2.0'		Wet brownish gray gravelly fine to coarse sand w/some silt, trace of organic matter.	A-2-4 (0)	
12" Recovery						
	2	2.0'		Saturated brownish gray fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
		4.0'		13" Recovery		
	3	4.0'		Saturated brownish gray coarse to fine sand w/trace of gravel and silt.	A-3 (0)	
		6.0'		17" Recovery		
	4	6.0'		Saturated brownish gray coarse to fine sand w/trace of gravel and silt.	A-1-b (0)	
		8.0'		19" Recovery		
(END)						

BORING NO. S # 2
SURFACE ELEV. + 4.34'

No blow counts boring done with geoprobe