

STATE OF DELAWARE
 DEPARTMENT OF TRANSPORTATION
 DIVISION OF HIGHWAYS

BORING NO. S # 6

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
 BORING LOCATION: STA. 1030+02, 33' Lt. CENTERLINE

R:24-56

DAILY PROGRESS	SAMPLE NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G. I.	REMARKS
1/4/05	1	1.0' 2.0'		Saturated brown organic silty fine sand w/some coarse sand, trace of gravel.	A-2-4 (0)	
23" Recovery						
	2	2.0' 4.0'		Saturated brownish gray fine sand w/some silt, trace of coarse sand and gravel.	A-2-4 (0)	
17" Recovery						
	3	4.0' 6.0'		Saturated brownish gray fine sand w/some coarse sand, trace of silt and gravel.	A-3 (0)	
22" Recovery						
	4	6.0' 8.0'		Saturated brownish gray fine to coarse sand w/trace of gravel and silt.	A-3 (0)	
22" Recovery						
(END)						

BORING NO. S # 6

SURFACE ELEV. + 4.36'

No blow counts boring done with geoprobe