

STATE OF DELAWARE
DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. S # 13

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
BORING LOCATION: STA. 1065+03, 33.2' Rt. CENTERLINE

R:25-32

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
1/4/05	1	0.8'	1	Wet loose brown fine sand w/some silt and coarse sand.	A-2-4 (0)	
			2			
			3			
		2.0'	3			
----- 22" Recovery -----						
	2	2.0'	6	Wet medium dense brown coarse to fine sand w/some silt, trace of gravel.	A-1-b (0)	
			7			
			8			
		4.0'	9			
----- 20" Recovery -----						
	3	4.0'	5	Saturated medium dense brown fine sand w/trace of coarse sand and silt.	A-3 (0)	
			7			
			11			
		6.0'	12			
----- 22" Recovery -----						
	4	6.0'	10	Saturated dense brown fine sand w/trace of coarse sand and silt.	A-3 (0)	
			13			
			18			
		8.0'	20			
----- 22" Recovery -----						

(END)

L18

BORING NO. S # 13
SURFACE ELEV. + 4.56'