

STATE OF DELAWARE
 DEPARTMENT OF TRANSPORTATION
 DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. D # 13

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
 BORING LOCATION: STA. 1069+38, 45' Rt. CENTERLINE

R:25-41

DAILY PROGRESS	SAMPLE NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
	1	1.0' 2.0'		Wet brown silty fine sand w/some coarse sand.	A-2-4 (0)	
	2	2.0' 4.0'		Wet brown silty fine sand w/some coarse sand.	A-2-4 (0)	
	3	4.0' 6.0'		Saturated brownish gray silt w/some fine sand and clay, trace of coarse sand.	A-4 (1)	
	4	6.0' 8.0'		Saturated brownish gray silt w/some clay, trace of fine sand.	A-4 (3)	
	5	8.0' 10.0'		Saturated grayish brown silt w/some coarse to fine sand, trace of gravel.	A-4 (0)	
(END)						

BORING NO. D # 13
 SURFACE ELEV. + 5.28'
 No blow counts boring done with geoprobe