

STATE OF DELAWARE
 DEPARTMENT OF TRANSPORTATION
 DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. S # 16

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS
 BORING LOCATION: STA. 1080+03, 41.3' Lt. CENTERLINE

R:25-47

DAILY PROGRESS	SAMPLE NO.	DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
1/4/05	1	1.0' 2.0'		Saturated brown silty fine sand w/some coarse sand, trace of organic matter.	A-2-4 (0)	
23" Recovery						
	2	2.0' 4.0'		Saturated brownish gray fine sand w/some silt and coarse sand.	A-2-4 (0)	
21" Recovery						
	3	4.0' 6.0'		Saturated brownish gray fine to coarse sand w/trace of silt and gravel.	A-3 (0)	
21" Recovery						
	4	6.0' 8.0'		Saturated brownish gray fine sandy silt w/trace of coarse sand.	A-4 (0)	
24" Recovery						
(END)						

Li

BORING NO. S # 16
 SURFACE ELEV. + 4.57'
 No blow counts boring done with geoprobe