

STATE OF DELAWARE  
 DEPARTMENT OF TRANSPORTATION  
 DIVISION OF HIGHWAYS

PAGE 2 OF 2

BORING NO. D # 1

CONTRACT: 24-112-01 S.R. 54 - MAINLINE IMPROVEMENTS  
 BORING LOCATION: STA. 1078+87, 160.5' Rt. CENTERLINE

Ri 25-48

DAILY PROGRESS	NO.	SAMPLE DEPTH	BLOWS/6"	SAMPLE DESCRIPTION	CLASS/G.I.	REMARKS
12/30/04	1	1.0' 2.0'		Saturated brownish gray silty fine sand w/some coarse sand, trace of organic matter.	A-2-4 (0)	
23" Recovery						
	2	2.0' 4.0'		Saturated brown fine sand w/some silt and coarse sand, trace of gravel.	A-2-4 (0)	
22" Recovery						
	3	4.0' 6.0'		Saturated brown fine sand w/some silt and coarse sand, trace of gravel.	A-2-4 (0)	
22" Recovery						
	4	6.0' 8.0'		Saturated brownish gray silt w/some fine sand, trace of coarse sand.	A-4 (0)	
23" Recovery						
	5	8.0' 10.0'		Saturated brownish gray silt w/some fine sand, trace of coarse sand.	A-4 (0)	
24" Recovery						

( END )

BORING NO. D # 1  
 SURFACE ELEV. + 2.90'  
 No blow counts boring done with geoprobe