

MAIL TO:
 WATER SUPPLY BRANCH
 DIVISION OF ENVIRONMENTAL CONTROL
 P.O. BOX 1401
 DOVER, DELAWARE 19903

STATE OF DELAWARE
 DEPARTMENT OF NATURAL RESOURCES
 AND ENVIRONMENTAL CONTROL

WELL COMPLETION REPORT M
 BE RETURNED 30 DAYS AFTER
 CONSTRUCTION DATE

WELL COMPLETION REPORT

Rj22-20

PLEASE PRINT

PERMIT NO. 91593 LOCAL ID _____
 OWNER Charles Krompton

CONSTRUCTION DATE 7-13-92
 PURPOSE: TEST PERMANENT
 USE: DOMESTIC AGRICULTURAL
 COMMERCIAL INDUSTRIAL
 IRRIGATION PUBLIC
 OBSERVATION DEWATERING
 HEAT PUMP RECHARGE HEAT PUMP SUPPLY
 OTHER (Specify) _____

IS THIS A REPLACEMENT WELL? YES NO
 ABANDONMENT DATE FOR OLD WELL 7-13-92
 ABANDONMENT METHOD Bentonite Clay

DRILLING METHOD
 AUGERED BORED CABLE TOOL
 DRIVEN JETTED AIR ROTARY
 MUD ROTARY REVERSE WASHED
 OTHER (Specify) _____
 TOTAL DEPTH DRILLED 293'

CASING SEQUENCE

	INNER	OUTER
CASING TOP	<u>24"</u>	
CASING BOTTOM	<u>283</u>	
CASING DIAMETER	<u>2"</u>	
CASING MATERIAL	<u>PVC</u>	

SCREEN SEQUENCE

	INNER	OUTER
SCREEN TOP	<u>283'</u>	
SCREEN BOTTOM	<u>293'</u>	
SCREEN DIAMETER	<u>2"</u>	
SCREEN MATERIAL	<u>PVC</u>	

WRITTEN APPROVAL FOR SCREENING/
 GRAVEL PACKING MORE THAN ONE AQU-
 IFER MUST BE OBTAINED FROM DNREC.

GROUT TYPE: CEMENT BENTONITE CLAY
 OTHER: _____
 FROM 3 TO 40 FEET
 NON-GROUT BACKFILL OF WELL ANNULUS
 TYPE None FROM _____ TO _____ FEET
 GRAVEL PACK: TYPE None
 FROM None TO _____ FEET
 STATIC WATER LEVEL: DATE 7-13-92
 _____ FT. (Below, above) GROUND SURFACE
 PUMPING WATER LEVEL: _____ FT. BELOW GRADE
 AFTER _____ HOURS AT _____ GPM.


WELL HEAD COMPLETION:
 TYPE: PITLESS ADAPTOR
 OTHER Cap
24 INCHES ABOVE GRADE.

TYPE OF PERMANENT PUMP INSTALLED

PUMP MANUFACTURE _____
 RATED CAPACITY (GPM) _____
 PUMP INTAKE SETTING _____ FT. BELOW GRADE

THE COMPLETED WELL IS?
 YES NO
 A. AT LEAST 15' FROM ANY FOUNDATION
 B. AT LEAST 50' FROM ANY SEPTIC TANK
 C. AT LEAST 10' FROM TOWN SEWER LINE
 D. AT LEAST 100' FROM THE NEAREST EDGE OF ANY TILE FIELD

THE NEAREST NEIGHBORS (CIRCLE ONE)
 (SEPTIC) TILE FIELD CESSPOOL OR PRIVY
 IS Septic FROM COMPLETED WELL.
 IS COMPLETED WELL LOCATED AS SHOWN ON APPLICATION FORM?
 IF NO, DESCRIBE LOCATION CHANGE OR OTHER COMMENT



DRILLERS LOG DESCRIPTION	TOP OF STRATA	BOTTOM OF S
<u>sand</u>	<u>0</u>	<u>30</u>
<u>clay</u>	<u>30</u>	<u>39</u>
<u>fine sand</u>	<u>39</u>	<u>145</u>
<u>clay & sand</u>	<u>145</u>	<u>170</u>
<u>sand</u>	<u>170</u>	<u>230</u>
<u>silt & clay</u>	<u>230</u>	<u>273</u>
<u>fine sand</u>	<u>273</u>	<u>293</u>
<u>sand</u>		

SUPPLEMENTAL DRILLERS LOG ATTACHED YES NO
 PAGE 1 OF _____ PAGES
 COMPANY NAME _____
 SIGNATURE OF DRILLER IN CHARGE: George J. Odrey DATE 7-13-