

Department of Natural Resources  
 Maryland Geological Survey  
 2300 St. Paul Street  
 Baltimore, Maryland 21218

6-127  
 10f2  
 Permit Number \_\_\_\_\_  
 Well Number 1  
 Company Engler  
Wilburn Unit  
 County Garrett

**COMPLETION REPORT**  
 (oil or gas well)

*This report must be submitted within 30 days after completion of the well*

**WELL DESCRIPTION - KIND OF WELL:**

(Oil, Gas, Other)

NAME & WELL NO.	Engler Exploration, Inc. #1 Wilburn Unit	Size of Casting and Tubing	Used in Drilling	Left in Well	Packers: Type, Size and Depth
ELEVATION:	2715 GR 2725 KB LEASE: Wilburn	8 5/8"	1631'	1631'	None
DRILLING COMMENCED:	5/20/88 DRILLING COMPLETED: 5/30/88				
PRODUCTION:	Plugged & Abandoned				
RESERVOIR PRESSURE	N/A psig N/A hrs.				
WELL TREATMENT:	(Shooting, Acidizing, Fracturing, Etc.)				
	N/A				PERFORATIONS A

**CEMENTING DATA: (Size Pipe, Depth, No. Bags, Date)**

5/25/88 - 8 5/8" 23# set at 1631'  
 Cemented w/235 sacks light cement with 7 sacks calcium chloride plus 60# flocele. Followed w/120 sacks standard bulk cement with 3 sacks calcium cholride plus 30# flocele. Good cement returns to surface.

**RESERVOIR PRESSURE AFTER TREATMENT:**

N/A

6/7/88 - Hole was plugged with 47 sacks of standard bulk cement plus 47 sacks pozmix "A" cement, 28 sacks gel, plus 450# salt cement. Plugs set interval: (4144-4023) (1677-1577) (100-surface) Gel plug interval: (4389-4144) (4023-1677) (1527-100) All cement plugs checked with wire line measurements.

**RESULTS AFTER TREATMENT:**

N/A

**REMARKS:**

Halliburton Job Log and Work Order of Plugging of Well Enclosed.

**GEOPHYSICAL LOGS (Type of Geophysical Logs Run on Well)**

Gamma Ray  
 Formation - Density  
 Neutron  
 Induction  
 Temperature

State of Maryland  
 Department of Natural Resources  
 Maryland Geological Survey  
 2300 St. Paul Street  
 Baltimore, Maryland 21218  
**GEOLOGICAL LOG**

2 of 2

Permit Number 146127  
 Well Number 1  
 Company Engler  
Wilburn Unit  
 County Garrett

FORMATION	TOP	BOTTOM	GAS AT	OIL AT	WATER AT (Fresh or Salt Water)	REMARKS
Water Sand	40'	46'	-	-	42'	1" stream
1st Riley S.S.	3725'	3743'	none	none	none	
2nd Riley S.S.	3810'	3821'	none	none	none	Reverse fault at 3811'
Benson S.S.	4073'	4094'	none	none	none	
TD 4389' Driller 4388' Logger						

This completion report is accurate to the best of my knowledge.

Date June 8, 1999

APPROVED Franklyn Engler

By President  
 (Title)

COMPANY Engler Exploration, Inc.