

Interval Sheet

Sheet No. _____

— Cuttings

— Core

— Water Well

--- Gas Well

From-To

From-To

From-To

From-To

From-To

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

-

Total Depth _____

OWNER: Charles Trimble
DRILLER: Ground Water, Inc.
COUNTY: Bath (Warm Springs)

VDMR #399
WWCR #7
Depth: 110'

SAMPLE EXAMINATION
(washed)

0 - 9 No sample (Static Water Level 8 feet)
9 - 18 Surface material (Bedrock estimated at 18 feet)
18 - 27 Shale, black, non-calcareous, traces of pyrite
(WATER REPT. 20 - 50)
27 - 45 Shale as above, some fine calcite seams and pyrite bands.
45 - 63 Shale as above
63 - 72 Shale as above, decrease in amount of pyrite
72 - 81 Shale as above
81 - 99 Shale as above, increase in amount of calcite
(WATER REPT. 90 - 110?)
99 - 110 Shale as above
110- Total depth

REMARKS

Probably all in Devonian Romney shale

Driller indicates water may contain gas as small bubbles were present in water.

VIRGINIA DIVISION OF MINERAL RESOURCES
Laurence H. Gardner II
June 14, 1961