



OWNER: U. S. Forest Service  
( Potts Creek Area)

VDMR: 1785

DRILLER: Frank W. Martin Drilling Co., Inc.

WWCR: 10

COUNTY: Craig (Paint Bank)

TOTAL DEPTH: 85'

### GEOLOGIC LOG

Depth in Feet

0 - 20	No samples.
20 - 30	Shale — black; fissile, hackly fracture, trace of quartz fracture filling.
30 - 40	"
40 - 50	" with vein calcite
50 - 60	Shale — black; fissile, hackly fracture, trace of quartz fracture filling.
60 - 70	"
70 - 80	" with trace of weathered sandstone.
80 - 85	No samples.

### GEOLOGIC SUMMARY

<u>Rock Unit</u>	<u>Age</u>
Millboro Formation	Middle Devonian

Virginia Division of Mineral Resources  
Thomas M. Gathright - Geologist  
January 24, 1967